



#1. The Bridge entrance into North Park, looking northeast



#2. Sacony Creek looking southeast



#3. Sacony Creek looking northwest



#4. The gravel Parking Lot looking northwest



#5. Service road leading to the Southeast end of North Park



#6. Trail leading into Mixed Larch woods



#7.
Walking path between north side of stream and parking lot



#8. Leftover erosion control measures



#9. Stormwater Basin between parking lot and stream



#10. Mixed Larch southwest of parking lot with invasive Norway Maple (Zone 9)



#11. Boy scout Trail looking west with adjacent stormwater basin



#12. Parking lot looking southeast and stormwater Basin in center



#13. Stormwater basin and Open field



#14. Rock with North Park description, adjacent to open field, north




#15. Planted tree with deer protection



#16. Gazebo in open field (Zone 2)



#17. Stormwater Basin near gazebo



#18. Manmade brick swale looking north



#19. Brick swale leading to Sacony Creek



#20. Bridge that extends over manmade brick swale



#21. Lined outlet and Sewage Treatment Plant outfall



#22. Reverse photo of lined outlet and Sewage Treatment Plant outfall



#23. Trail to the west of Sacony Creek



Bridge remnant, looking east



#25. Upstream of Sacony Creek



#26. Downstream with riffle monitoring location




#27. Deer trail in riparian corridor



#28. Trash on east side of stream; still KU borough property



#29. Riffle monitoring location looking downstream



#30. Riffle monitoring location looking upstream



#31. Wetlands adjacent to stream



#32. Deciduous Dry Oak forest, looking west (Zone 8)



#33. Sacony Creek looking downstream



#34. Neighboring house across Sacony Creek



#35. Wetlands containing trash adjacent to stream




#36. Downstream of Sacony Creek



#37. Wetlands




#38. Former location of Long Dam Road bridge



#39. Looking downstream at former bridge location



#40. Looking upstream at former bridge location



#41. Private driveway looking south



#42. Neighbors misplaced private property sign west of Long Dam Road



#43. Old tires along Long Dam Road in Southwest successional woods



#44. Krumsville Road and riparian buffer looking east



#45. Riparian wetland along Long Dam Road



#46. Looking upstream



#47. Looking downstream



#48. Riparian wetland along Long Dam Road



#49. Neighbors no trespassing sign



#50. Riparian floodplain with vehicle tracks, looking north



#51. Abandoned couch, looking west



#52. Riparian floodplain with vehicle tracks, looking north



#53. Evergreens at property corner



#54. Long Dam Road, looking west



#55. Tree cavity for wildlife



#56. Sycamore along Krumsville Road and Northeast isolated woodland



#57. Former Service Road looking southwest



#58. Private driveway looking south



#59. Private driveway approaching neighbor residents



#60. Tree cutting activity



#61. Tree cutting activity



#62. View from neighbor residence looking Northeast



#63. Neighbor shed



#64. Neighbor residence looking north



#65. View from neighbor residence, looking south



#66. Driveway leading up to neighbor residence



#67 Junk and a fire pit on property of neighbor residence



#68. Trail leading from neighbor residence, looking west



#69. No hunting sign



#70. Manmade brick swale



#71 Manmade brick swale along east side of sewer plant



#72 Open field for recreational use



#73 Trail at the open field



#74 Foot bridge that extends over the manmade brick swale with restrooms



#75 Picnic gazebo within open field



#76 Restrooms



#77 Trail at the open field



#78 Manmade brick swale that travels to the Sacony Creek



#79 Sewer plant and sewer line manhole



#80 Stormwater outlet from Sewage Treatment Plant



#81 Gravel walking trail leading past the Restrooms



#82 Gravel walking trail leading past the Restrooms reverse angle



#83 Sewer Treatment Plant, looking west



#84 Sewer Treatment Plant sign



#85 Sewer Treatment Plant



#86 Dumped logs



#87 Service Road leading to dump and filled area



#88 Service Road with mixed Larch in the background



#89 Interface of filled area with successional disturbed woods



#90 Interface of filled area with Dry Oak forest (Zone 8)



#91 Dump and filled area



#92 Interface of filled area with successional disturbed



#93 Neighbors no trespassing sign next to dumping site



#94 Dry Oak forest (Zone 8) looking at dump and filled area



#95 Neighbor property ravine



#96 View of neighbor's property



#97 Neighbor property farm land and field



#98 Border of North park containing junk



#99 Electric fence for buffalo along property boundary looking east



#100 No hunting sign adjacent to buffalo pen



#101 Fridge that was junked within Dry Oak woods (Zone 8)



#102 Buffalo farm from property boundary looking south



#103 Buffalo farm to the west, adjacent to of North park



#104 Electric fence surrounding buffalo farm, looking west



#105 Service road leading to water tower



#106 Fence that contains water tower



#107 Service Road leading to restricted water tower



#108 Service Road between neighbors electric fence and water tower area



#109 View across neighbors pasture toward Kutztown water tower



#110 Improved Service Road at the restricted water tower area and communication tower area



#111 Neighbors electric fences and pastures



#112 Improved Service Road coming back down from water tower



#113 Communication tower



#114 Walking trail coming down from water tower area



#115 Improved Service Road located SW looking up



#116 drainage culvert



#117 Service Road leading to restricted water tower area, looking southwest



#118 Improved Service Road and walking trail, looking northeast



#119 Service road and walking trail, looking southeast



#120 Unimproved Service Road and walking trail in mixed Larch (Zone 9)



#121 Walking trail in successional disturbed, looking southeast



#122 Walking trail continued in successional disturbed, looking southeast



#123 Southeast successional disturbed forest (Zone 10)



#124 Improved Service Road and walking trail, looking northwest



#125 Unimproved Service Road and walking trail, looking southwest



#126 Improved Service Road and walking trail, looking northwest



#127 Mowed maintenance area under phone lines, looking northwest



#128 Sacony Creek with Krumsville Road in background



#129 View from mowed maintenance area and phone lines crossing Sacony Creek



#130 Stormwater outfall at Sacony Creek



#131 Riparian area of Sacony Creek along Krumsville Road



#132 Utility service manhole



#133 Marker for utility corridor



#134 Improved Service Road and walking trail, looking southwest



#135 Utility corridor blocked by boulders looking east



#136 Boulders blocking hikers from utility corridor, looking west



#137 Gated improved Service Road and walking trail



#138 Utility Service box



#139 Improved Service Road and walking trail near park entrance, looking northwest



#140 Improved Service Road and walking trail near park entrance, looking southeast



#141 Boy scout walking trail entrance



#142 Boy scout walking trail, looking southwest



#143 Boy scout walking trail along mixed Larch trees (Zone 9)



#144 Mixed Larch Tree silhouettes (Zone 9)



#145 Larch tree with woodpeckers wells



#146 Mixed Larch silhouettes



#147 Lid on developed spring adjacent to restrooms



#148 Outlet for developed spring adjacent to manmade brick swale



#149 Invasive species in riparian area along Sacony Creek



#150 Eroded stream bank on borough property along Sacony Creek adjacent to neighbor's property



#151 Lined outlet for Parking lot stormwater outfall



#152 Detention basin stormwater outfall



#153 Walking trail along riparian buffer for Sacony Creek



#154 Sacony Creek with unnamed tributary between neighbor properties



#155 Dumping along Sacony Creek on neighboring properties